
DESIGNATION LIST

DESIGNATION	DESCRIPTION		
C1,C2 C3,C4 C5,C6 C7-C10 CP1 CP2,CP3	4,7 mf 25v rd.tant. 22 mf 6v '' '' 470 mf 6v ax.electl mf 50v ax.elect. 220 mf 25v ax.electl mf 50v ax.er.		
RI,R2 R3,R4 R5-R8 U1,U 2	2.7K\(\Omega\) 1/4w 5\% CRBN 27\(\Omega\) 1/2w 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4		
JI J2	3 PIN STRT KKI56 4 " " " " " " " " " " " " " " " " " " "		
HSA1,2 MHI-MH 4	HEATSINK ASSY. HEYCO BUSHING		



CROSS REFERENCE LIST

DESCRIPTION	<u>at y</u>	DESIGNATION	PART NO
1mf 50v ax cr	6	C7-C10, CP2,CP3	0986-008001100
4.7 mf 25v rd.tant 22 mf 6v 220mf 25v axelec 470mf 6v	2	CI,C2 C3,C4 CPI C5,C6	0986-00800-3100 0986-00800-1600 0986-00800-3200 0986-00800-1700
1Ω1/2w 5% 27Ω1/4w 27K	2 2	R5-R8 R3,R4 R1,R2	0062-026D3-1XXX 0062-068B3-1XXX 0062-199B3-1XXX
MB3730	2	U1,U2	0066-188xx-xx4x
2 PIN STRT KKI56 3 '' '' '' 4 '' ''	1 2 1	J2 J1,J2 J1	3000-16367-0200 3000-16367-0300 3000-16367-0400
HEATSINK ASSY	2	HSAI, HSA2	0986-00804-1800
HEYCO BUSHING	4	MH1- M H4	0017-00042-0014
PC BOARD	1		A080-90910-D000

